

Kontakt / Contact

Aadress: Lennuliiklusteeninduse
Aktiaselts
Lennundusteabe
osakond
Kanali põik 3
Rae küla, Rae vald
10112 Harjumaa
Estonia
Tel: +372 671 0255
Email: aip@eans.ee
URL: aim.eans.ee

AIP Supplement for Estonia**AIP Lisa / AIP SUP**

14/2026
Kehtiv alates
Effective from
10 AUG 2026
kuni / to 01 SEP 2026
Avaldatud
Published on
23 JUL 2026

**Kuressaare lennuvälja liiklusala
rekonstrueerimistööd****Reconstruction Works of Kuressaare
Aerodrome Movement Area****1 Üldine**

See AIP Lisa täiendab järgmist AIP-i osa: AD 2 EEKE.

AIP Lisa võimalikud muudatused avaldatakse NOTAM-iga.

2 Periood

10. august 2026 kuni 31. august 2026.

3 Eesmärk

Kuressaare lennuvälja liiklusala rekonstrueerimine.

4 Kirjeldus

Kuressaare lennuvälja liiklusala suletakse rekonstrueerimistööde tõttu.

Rekonstrueerimise käigus:

- Uuendatakse liiklusala katend (v.a rada 05/23);
- Rekonstrueeritakse raja 35 läve tagasipöördeala;
- Uuendatakse liiklusala markeering;
- Ootejoontele A ja B rajatakse raja hoiatustuled (RGL);
- Raja 17/35 ääre-, läve- ja lõputuled (REDL, RTHL, RENL), PAPI tuled ning ruleerimisteede ääretuled ja viitade valgustus vahetatakse LED-valgustite vastu;
- Kaasajastatakse tulede juhtimissüsteem koos PCL funktsiooni lisandumisega.

5 Piirangud

Rekonstrueerimistööde perioodil on Kuressaare lennuväljal kehtestatud järgmised piirangud:

- Lennuvälja liiklusala on suletud;
- Lennuväli on lennutegevuseks suletud;
- Lennuväli ja Kuressaare AFIS-üksus on suletud;
- Lennuvälja tuletõrjekategooria ei ole saadaval;
- ILS IWA ei ole kasutusel;
- Tankimine ja käitlemine ei ole saadaval;
- Madallähenemised raja kohal on keelatud;
- Ülelend madalamal kui 700 ft AMSL on keelatud.

1 General

This AIP SUP supplements the following portion of the AIP: AD 2 EEKE.

Possible changes to AIP SUP shall be published by NOTAM.

2 Period

10 AUG 2026 to 31 AUG 2026.

3 Purpose

Reconstruction of Kuressaare aerodrome movement area.

4 Description

Kuressaare aerodrome movement area will be closed due to reconstruction works.

During the reconstruction:

- Manoeuvring area pavement will be renewed (except RWY 05/23);
- RWY 35 THR turning pad will be reconstructed;
- Manoeuvring area markings will be renewed;
- RGL lights will be installed at holding positions A and B;
- RWY 17/35 REDL, RTHL, RENL, PAPI lights, TWY edge lights and illuminated signs will be replaced with LED lights;
- The airfield lighting control system will be upgraded, including the addition of the PCL function.

5 Restrictions

During the reconstruction period, the following restrictions will apply at Kuressaare aerodrome:

- Aerodrome movement area will be closed;
- Aerodrome will be closed for flight operations;
- The aerodrome and Kuressaare AFIS unit will be closed;
- Aerodrome fire fighting category will not be available;
- ILS IWA will not be in use;
- Fuelling and handling will not be available;
- Low approaches over the runway will be prohibited;
- Overflight of the aerodrome below 700 ft AMSL will be prohibited.

TÜHJAKS JÄETUD
PAGE INTENTIONALLY LEFT BLANK